


Mogi Guaçu, October 13, 2021

To whom it may concern,

**Ref.: Process Flowchart – Steviol glycosides**

One of our control measures is the Drying step to ensure the removal of alcohols used in the process. Other control measures are sieves, which guarantee the absence of contaminants above 2,0 mm, and metal detectors for ferrous, non-ferrous and stainless-steel fragments. The flowchart for the ingredient mentioned above is shown below:



We are at your disposal for any further information.

Best regards,

Quality Assurance